

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果						底質調査結果				備考	
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度(Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs
1	1	小舟沼 (2)	福島市	R5. 7. 26	晴	0. 25	流入口	×	×	×	×	×	×	×	10. 0	47. 5	1, 600	117, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	53. 8	5, 600	557, 000	
								20. 0	47. 0	2, 800									
								30. 0	46. 1	400									
								40. 0	47. 5	20									
							取水口	0. 15	0. 1	6. 0	87. 1	200	<1	—	10. 0	58. 1	14, 000	4, 109, 000	
								20. 0	57. 8	23, 000									
								30. 0	55. 4	29, 000									
								40. 0	42. 1	3, 900									
2	2	土合沼	福島市	R5. 8. 4	晴	0. 12	流入口	0. 37	0. 1	27. 0	15. 1	23	<1	—	6. 7	65. 1	1, 100	28, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	54. 2	2, 800	164, 000	
							取水口	1. 35	0. 5	35. 3	10. 1	17	<1	—	10. 0	53. 9	3, 300	191, 000	
3	3	沼ノ上沼	福島市	R5. 7. 24	晴	0. 13	流入口	1. 98	0. 5	38. 8	21. 3	8	<1	—	2. 3	33. 9	6, 200	134, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	56. 9	30, 000	3, 190, 000	
								20. 0	49. 8	23, 000									
							取水口	0. 68	0. 1	81. 7	7. 1	5	<1	—	10. 0	65. 2	30, 000	5, 604, 000	
								20. 0	57. 1	50, 000									
								30. 0	52. 8	21, 000									
								40. 0	45. 4	590									
4	4	田沢沼	福島市	R5. 7. 24	晴	0. 16	流入口	1. 32	0. 5	53. 5	6. 4	4	<1	—	2. 7	21. 8	2, 700	88, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	32. 4	3, 800	420, 000	
								20. 0	37. 4	150									
							取水口	2. 19	0. 5	58. 5	9. 1	3	<1	—	10. 0	41. 2	17, 000	3, 608, 000	
20. 0	36. 2	23, 000																	
5	5	天王寺沼	福島市	R5. 7. 26	晴	0. 19	流入口	1. 35	0. 5	66. 0	6. 4	4	<1	—	5. 0	40. 4	1, 300	48, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	59. 6	2, 800	735, 000	
								20. 0	57. 4	3, 600									
								30. 0	55. 4	4, 600									
								40. 0	54. 8	2, 600									
							取水口	3. 78	0. 5	85. 5	1. 5	4	<1	—	10. 0	53. 4	3, 300	889, 000	
								20. 0	50. 6	4, 900									
								30. 0	52. 8	6, 500									
								40. 0	51. 6	160									

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果							底質調査結果				備考							
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	S S (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)	放射性物質 底質表面濃度 (Bq/m ²)								
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs	¹³⁷ Cs								
13	6	上の池	二本松市	R5. 7. 31	晴	0. 18	流入口	1. 80	0. 5	27. 3	11. 8	30	<1	—	6. 7	45. 0	14, 000	817, 000	帰還困難区域外							
							湖心部	—	—	—	—	—	—	—	8. 0	41. 2	6, 600	491, 000								
							取水口	1. 67	0. 5	31. 8	12. 3	29	<1	—	10. 0	37. 7	2, 900	1, 269, 000								
															20. 0	35. 2	8, 900									
14	7	高平 2 号	二本松市	R5. 8. 1	曇	0. 19	流入口	0. 84	0. 1	34. 0	14. 5	11	<1	—	10. 0	55. 2	7, 000	1, 329, 000	帰還困難区域外							
															20. 0	56. 5	9, 700									
															30. 0	50. 9	5, 800									
															40. 0	45. 3	310									
							湖心部	—	—	—	—	—	—	—	10. 0	49. 5	6, 700	2, 831, 000								
															20. 0	51. 1	8, 500									
															30. 0	50. 5	12, 000									
															40. 0	48. 5	14, 000									
							取水口	0. 79	0. 1	25. 0	23. 0	33	<1	—	10. 0	46. 9	5, 000	1, 762, 000								
															20. 0	42. 4	5, 600									
															30. 0	42. 9	10, 000									
															15	8	方入内			二本松市	R5. 7. 31	晴	0. 23	流入口	1. 55	0. 5
湖心部	—	—	—	—	—	—	—	10. 0	49. 4	4, 900	562, 000															
								20. 0	41. 8	2, 400																
16	9	沼田	伊達市	R5. 7. 27	晴	0. 26	取水口	1. 96	0. 5	>100	2. 0	3	<1	—	4. 7	26. 8	770	44, 000	帰還困難区域外							
							流入口	0. 09	表層	39. 5	4. 1	—	—	—	4. 7	24. 7	1, 100	65, 000								
															湖心部	—	—	—		—	—	—	10. 0	56. 8	8, 800	2, 773, 000
																							20. 0	53. 6	17, 000	
																							30. 0	50. 3	20, 000	
							取水口	2. 03	0. 5	34. 0	11. 3	27	<1	—	10. 0	56. 4	6, 800	3, 895, 000								
															20. 0	57. 1	12, 000									
															30. 0	54. 7	32, 000									
40. 0	50. 2	13, 000																								
17	10	芳沼入	伊達市	R5. 7. 25	晴	0. 19	流入口	0. 06	表層	11. 3	68. 1	—	—	—	4. 3	28. 9	180	9, 000	帰還困難区域外							
							湖心部	—	—	—	—	—	—	—	6. 7	43. 0	3, 700	191, 000								
							取水口	0. 54	0. 1	41. 5	17. 4	10	<1	—	10. 0	52. 6	4, 500	1, 514, 000								
															20. 0	47. 8	6, 000									
															30. 0	54. 4	14, 000									

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モニ No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果						底質調査結果				備考		
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	S S (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs	
22	15	赤貝	伊達市	R5. 7. 28	晴	0. 25	流入口	0. 80	0. 1	58. 2	3. 2	8	<1	—	10. 0	55. 8	4, 500	257, 000	帰還困難区域外	
															20. 0	51. 7	260			
															30. 0	49. 9	20			
							湖心部	—	—	—	—	—	—	—	10. 0	41. 1	1, 700	569, 000		
															20. 0	47. 3	6, 300			
															10. 0	55. 4	9, 800			
							取水口	0. 60	0. 1	58. 0	0. 9	9	<1	—	20. 0	59. 4	31, 000	2, 520, 000		
															30. 0	56. 0	10, 000			
															40. 0	41. 8	140			
23	16	堀沢沼	伊達市	R5. 7. 28	晴	0. 14	流入口	0. 66	0. 1	>100	6. 4	3	<1	—	4. 7	36. 3	4, 800	199, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	2. 3	50. 6	7, 900	118, 000		
							取水口	1. 23	0. 5	>100	5. 0	4	<1	—	8. 0	48. 1	4, 400	246, 000		
24	17	台	伊達市	R5. 7. 27	晴	0. 11	流入口	0. 37	0. 1	53. 5	5. 6	13	<1	—	10. 0	51. 2	1, 400	824, 000	帰還困難区域外	
															20. 0	49. 4	1, 500			
															30. 0	48. 5	2, 400			
															40. 0	46. 6	5, 600			
							湖心部	—	—	—	—	—	—	—	—	10. 0	57. 4	1, 600		417, 000
																20. 0	54. 8	2, 600		
																30. 0	51. 5	2, 400		
																40. 0	51. 2	340		
							取水口	0. 52	0. 1	50. 0	6. 2	12	<1	—	10. 0	59. 6	1, 700	356, 000		
															20. 0	58. 2	2, 700			
															30. 0	56. 3	1, 800			
															40. 0	53. 9	260			
26	18	松沢上池	川俣町	R5. 8. 10	晴	0. 19	流入口	0. 06	表層	78. 3	10. 6	—	—	—	6. 3	51. 9	910	36, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	10. 0	53. 8	3, 900	755, 000		
															20. 0	51. 8	7, 600			
															30. 0	49. 0	25			
							取水口	0. 89	0. 1	43. 0	8. 2	7	<1	—	10. 0	53. 5	3, 900	344, 000		
															20. 0	48. 5	1, 400			
															30. 0	45. 5	16			

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果						底質調査結果				備考		
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	S S (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs	
6	19	大久保池	郡山市	R5. 8. 4	晴	0. 15	流入口	1. 34	0. 5	2. 0	514. 0	420	<1	—	10. 0	45. 3	480	136, 000	帰還困難区域外	
															20. 0	38. 7	390			
															30. 0	36. 5	630			
							湖心部	—	—	—	—	—	—	7. 3	40. 5	490	33, 000			
							取水口	1. 08	0. 5	2. 0	470. 8	400	<1	—	5. 3	51. 7	2, 300	73, 000		
7	20	荒池	郡山市	R5. 8. 3	晴	0. 19	流入口	0. 97	0. 1	20. 3	27. 9	15	<1	—	2. 0	33. 5	16, 000	351, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	10. 0	54. 1	9, 200	603, 000		
							取水口	1. 81	0. 5	22. 5	19. 6	12	<1	—	5. 0	42. 6	6, 000	260, 000		
8	21	南田山田池-1号	郡山市	R5. 8. 3	晴	0. 16	流入口	0. 41	0. 1	53. 0	5. 0	7	<1	—	10. 0	53. 1	2, 300	474, 000	帰還困難区域外	
															20. 0	49. 9	3, 000			
															30. 0	46. 2	1, 700			
															40. 0	44. 1	35			
							湖心部	—	—	—	—	—	—	—	10. 0	55. 6	2, 800	651, 000		
															20. 0	55. 4	3, 600			
															30. 0	53. 4	4, 800			
															40. 0	51. 0	370			
							取水口	0. 42	0. 1	48. 6	6. 5	11	<1	—	10. 0	53. 5	2, 300	647, 000		
															20. 0	50. 9	2, 600			
															30. 0	51. 4	4, 100			
															40. 0	45. 0	1, 200			
9	22	新池	須賀川市	R5. 8. 2	晴	0. 10	流入口	0. 49	0. 1	24. 8	10. 0	43	<1	—	10. 0	47. 3	2, 200	361, 000	帰還困難区域外	
															20. 0	45. 9	2, 900			
							湖心部	—	—	—	—	—	—	—	10. 0	51. 2	3, 500	1, 089, 000		
															20. 0	50. 4	4, 000			
															30. 0	45. 6	5, 600			
															40. 0	49. 4	2, 400			
							取水口	0. 57	0. 1	29. 0	9. 1	20	<1	—	10. 0	47. 7	3, 700	964, 000		
															20. 0	55. 8	4, 500			
30. 0	51. 6	5, 900																		
40. 0	47. 0	1, 000																		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果							底質調査結果				備考
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)	放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs	¹³⁷ Cs	
10	23	古戸大池	須賀川市	R5. 8. 2	晴	0. 12	流入口	1. 15	0. 5	50. 0	7. 0	9	<1	—	3. 3	22. 0	200	8, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	9. 0	47. 4	2, 000	136, 000	
							取水口	0. 73	0. 1	49. 2	5. 5	5	<1	—	10. 0	62. 0	3, 600	955, 000	
															20. 0	61. 9	4, 400		
															30. 0	59. 9	5, 200		
															40. 0	58. 6	5, 400		
27	24	中核工業団地3号調整池	泉崎村	R5. 8. 1	晴	0. 12	流入口	2. 47	0. 5	41. 0	9. 6	21	<1	—	4. 7	37. 2	2, 200	100, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	7. 3	60. 3	13, 000	467, 000	
							取水口	1. 98	0. 5	62. 5	2. 3	3	<1	—	7. 7	64. 3	35, 000	1, 077, 000	
11	25	玉野	相馬市	R5. 7. 21	雨	0. 26	流入口	0. 67	0. 1	39. 5	16. 0	20	<1	—	5. 0	55. 5	2, 900	76, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	54. 6	3, 200	561, 000	
															20. 0	51. 7	3, 000		
															30. 0	51. 9	3, 300		
							取水口	0. 95	0. 1	50. 5	8. 2	12	<1	—	2. 7	34. 6	3, 200	93, 000	
12	26	一本木	相馬市	R5. 7. 21	雨	0. 16	流入口	1. 59	0. 5	93. 0	6. 4	1	<1	—	10. 0	33. 7	440	44, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	6. 0	39. 3	490	27, 000	
							取水口	2. 11	0. 5	>100	5. 9	2	<1	—	10. 0	38. 7	510	128, 000	
															20. 0	42. 9	970		
28	27	西の沢	広野町	R5. 7. 17	晴	0. 10	流入口	0. 87	0. 1	94. 0	4. 1	9	<1	—	3. 0	26. 1	230	9, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	4. 3	34. 4	620	25, 000	
							取水口	1. 01	0. 5	>100	2. 2	2	<1	—	10. 0	59. 5	1, 100	249, 000	
															20. 0	55. 6	1, 200		
															30. 0	57. 2	2, 500		
29	28	須賀作第2	檜葉町	R5. 7. 17	晴	0. 13	流入口	1. 71	0. 5	26. 2	12. 8	18	<1	—	10. 0	36. 4	1, 400	281, 000	帰還困難区域外
							20. 0	42. 1	1, 800										
							湖心部	—	—	—	—	—	—	—	10. 0	46. 1	2, 500	391, 000	
															20. 0	50. 1	3, 300		
															30. 0	48. 0	150		
							取水口	2. 01	0. 5	24. 8	24. 5	19	<1	—	10. 0	49. 5	3, 500	469, 000	
															20. 0	46. 1	3, 800		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果							底質調査結果				備考				
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)	放射性物質 底質表面濃度 (Bq/m ²)					
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs	¹³⁷ Cs					
30	29	石湯第1 (旧石湯第2)	檜葉町	R5. 7. 17	晴	0. 24	流入口	1. 62	0. 5	61. 4	2. 9	8	<1	—	10. 0	49. 5	4, 700	308, 000	帰還困難区域外				
							湖心部	—	—	—	—	—	—	—	20. 0	49. 4	240						
								取水口	2. 44	0. 5	60. 1	4. 5	3	<1	—	10. 0	48. 9	3, 300		218, 000			
									20. 0	44. 1	45	10. 0	51. 2	3, 600	218, 000								
									20. 0	36. 3	31	20. 0	36. 3	31									
							31		30	汐ノ作第1	檜葉町	R5. 7. 18	晴	0. 14	流入口	1. 19	0. 5	100. 0		0. 3	2	<1	—
湖心部	—	—	—	—	—	—		—							4. 0	47. 8	820	24, 000					
取水口	1. 69	0. 5	100. 0	0. 3	2	<1		—							6. 0	50. 8	6, 700	267, 000					
32	31	風呂ヶ沢	檜葉町	R5. 7. 17	晴	0. 17		流入口							0. 95	0. 1	32. 5	14. 1	22	<1	—	10. 0	64. 1
							湖心部	—	—	—	—	—	—	—	20. 0	60. 8	2, 700	179, 000					
								取水口	0. 88	0. 1	33. 0	12. 6	28	<1	—	10. 0	73. 5		5, 500	325, 000			
									20. 0	67. 0	1, 100	30. 0	65. 2	98	40. 0	66. 1	82		10. 0		72. 6	8, 800	325, 000
									20. 0	66. 6	2, 500	30. 0	49. 3	69	20. 0	66. 6	2, 500	30. 0	49. 3		69		
									33	32	焼野	檜葉町	R5. 7. 18	曇	0. 11	流入口	0. 48	0. 1	49. 8	6. 4	15	<1	
湖心部	—	—	—	—	—	—										—	10. 0	50. 3	2, 500	805, 000			
	20. 0	47. 4	3, 600	30. 0	44. 2	4, 800	10. 0									50. 6	1, 900	705, 000					
	取水口	1. 47	0. 5	50. 1	8. 7	11	<1	—								20. 0	47. 9		2, 500		705, 000		
30. 0		44. 0	4, 800	70. 0	32. 3	20	2, 000																
70		33	目倉沢第1	浪江町	R5. 7. 11	晴	0. 58	流入口								0. 15	0. 1	85. 0	1. 5	<1		<1	—
	湖心部							—	—	—	—	—	—	—	10. 0	54. 0	9, 000	490, 000					
	取水口							0. 50	0. 1	30. 6	8. 7	21	<1	—	10. 0	50. 1	6, 400	389, 000					

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果						底質調査結果				備考		
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs	
71	34	古堤	浪江町	R5. 7. 14	曇	0. 64	流入口	0. 73	0. 1	10. 5	7. 2	13	<1	—	10. 0	45. 6	7, 800	482, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	—	10. 0	62. 6	20, 000		1, 882, 000
								20. 0	59. 9	20, 000										
								30. 0	61. 8	3, 600										
								40. 0	65. 8	170										
							取水口	1. 19	0. 5	11. 0	92. 2	11	<1	—	10. 0	56. 2	19, 000	2, 668, 000		
								20. 0	55. 4	19, 000										
30. 0	54. 2	13, 000																		
72	35	堤上第 1	浪江町	R5. 7. 13	晴	0. 25	流入口	0. 10	表層	6. 0	68. 1	180	<1	—	6. 3	51. 7	2, 100	86, 000	帰還困難区域外 (R5. 3. 31解除)	
							湖心部	—	—	—	—	—	—	—	5. 7	55. 1	2, 100	66, 000		
							取水口	0. 13	0. 1	9. 0	59. 6	75	<1	—	7. 7	51. 8	3, 600	170, 000		
74	36	川添	浪江町	R5. 7. 12	晴	0. 16	流入口	×	×	×	×	×	×	×	6. 0	44. 1	610	29, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	6. 0	54. 3	2, 100	73, 000		
							取水口	0. 05	表層	42. 2	1. 0	—	—	—	5. 3	34. 9	910	49, 000		
75	37	麦ノ沢第 1	浪江町	R5. 7. 14	雨	2. 02	流入口	0. 78	0. 1	18. 4	21. 3	19	<1	—	6. 7	35. 6	14, 000	911, 000	帰還困難区域外 (R5. 3. 31解除)	
							湖心部	—	—	—	—	—	—	—	—	10. 0	47. 3	43, 000		6, 958, 000
								20. 0	47. 1	44, 000										
								30. 0	38. 2	7, 000										
							取水口	1. 40	0. 5	40. 3	21. 7	19	<1	—	10. 0	39. 4	56, 000	10, 033, 000		
								20. 0	40. 9	37, 000										
								30. 0	47. 8	30, 000										
76	38	堤上第 2	浪江町	R5. 7. 13	晴	0. 14	流入口	0. 65	0. 1	13. 3	34. 1	18	<1	—	7. 7	44. 6	8, 800	521, 000	帰還困難区域外 (R5. 3. 31解除)	
							湖心部	—	—	—	—	—	—	—	—	10. 0	43. 1	10, 000		2, 033, 000
								20. 0	53. 3	19, 000										
							取水口	0. 77	0. 1	16. 2	23. 9	6	<1	—	10. 0	56. 9	17, 000	3, 145, 000		
								20. 0	55. 0	23, 000										
								30. 0	50. 6	15, 000										
77	39	大日向第1	浪江町	R5. 7. 13	晴	0. 15	流入口	2. 33	0. 5	>100	3. 1	1	<1	—	9. 0	44. 1	1, 800	123, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	5. 7	38. 3	930	46, 000		
							取水口	2. 45	0. 5	>100	2. 2	1	<1	—	8. 7	44. 9	1, 200	80, 000		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果							底質調査結果				備考
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)	放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs	¹³⁷ Cs	
78	40	百間沢	浪江町	R5. 7. 11	晴	0.09	流入口	4.32	0.5	61.0	2.2	4	<1	—	10.0	46.4	1,100	84,000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10.0	55.6	2,800	272,000	
															20.0	51.1	1,500		
															30.0	51.3	65		
							取水口	3.17	0.5	52.0	3.0	5	<1	—	10.0	57.0	2,800	305,000	
															20.0	55.6	2,300		
30.0	49.4	210																	
79	41	北谷地	浪江町	R5. 7. 12	曇	1.01	流入口	1.34	0.5	50.0	7.5	1	<1	—	6.3	54.2	12,000	432,000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10.0	52.4	3,100	173,000	
															20.0	56.2	210		
							取水口	2.31	0.5	37.5	11.3	6	<1	—	10.0	56.3	7,600	619,000	
															20.0	57.7	4,500		
							80	42	聖沢	浪江町	R5. 7. 14	小雨	0.38	流入口	1.42	0.5	99.0	0.9	
湖心部	—	—	—	—	—	—								—	5.7	43.1	1,500	65,000	
取水口	2.00	0.5	>100	1.7	<1	<1								—	10.0	49.2	4,200	595,000	
															20.0	45.6	4,400		
82	43	関ノ倉	浪江町	R5. 7. 13	晴	1.02	流入口	0.92	0.1	23.2	34.8	27	<1	—	10.0	52.0	8,000	1,723,000	帰還困難区域外
															20.0	51.6	10,000		
															30.0	51.9	9,800		
							湖心部	—	—	—	—	—	—	—	10.0	55.0	8,000	1,246,000	
															20.0	52.9	12,000		
															30.0	54.9	2,700		
							取水口	1.42	0.5	13.3	46.5	20	<1	—	10.0	54.0	7,600	1,684,000	
															20.0	59.0	11,000		
															30.0	55.0	19,000		
84	44	小和田	浪江町	R5. 7. 14	曇	0.16	流入口	0.25	0.1	16.6	4.2	35	<1	—	6.0	64.7	2,900	73,000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	8.0	66.2	2,400	65,000	
							取水口	0.71	0.1	21.8	0.7	11	<1	—	10.0	64.8	3,100	125,000	
															20.0	57.8	280		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果						底質調査結果				備考		
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)	
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs	
85	45	小高瀬	浪江町	R5. 7. 13	晴	0. 18	流入口	2. 18	0. 5	>100	4. 8	4	<1	—	6. 7	43. 8	3, 000	153, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	10. 0	64. 4	4, 900	805, 000		
								20. 0	58. 0	5, 600										
								30. 0	55. 6	5, 500										
								40. 0	57. 0	400										
							取水口	2. 51	0. 5	66. 0	2. 8	6	<1	—	10. 0	54. 7	3, 900	901, 000		
								20. 0	51. 1	4, 700										
30. 0	49. 1	5, 600																		
68	46	寺内迫	双葉町	R5. 7. 20	晴	2. 76	流入口	0. 02	表層	8. 9	55. 3	—	—	—	5. 3	51. 9	44, 000	1, 280, 000	帰還困難区域外 (R4. 8. 30解除)	
							湖心部	—	—	—	—	—	—	—	10. 0	60. 6	73, 000	8, 390, 000		
								20. 0	59. 3	71, 000										
								30. 0	58. 7	31, 000										
							取水口	0. 12	0. 1	32. 0	6. 4	7	2	<1	7. 7	40. 9	38, 000	2, 321, 000		
47	47	新溜	大熊町	R5. 7. 31	晴	0. 72	流入口	0. 19	0. 1	33. 2	14. 1	9	<1	—	5. 0	33. 7	3, 800	211, 000	帰還困難区域外 (R4. 6. 30解除)	
							湖心部	—	—	—	—	—	—	—	10. 0	48. 0	8, 000	565, 000		
							取水口	0. 12	0. 1	10. 3	42. 1	90	4	3. 0	10. 0	50. 6	11, 000	2, 906, 000		
															20. 0	49. 7	33, 000			
49	48	寺屋敷	大熊町	R5. 7. 28	晴	0. 46	流入口	×	×	×	×	×	×	×	5. 0	28. 7	2, 600	150, 000	帰還困難区域外 (R4. 6. 30解除)	
							湖心部	—	—	—	—	—	—	—	—	5. 0	34. 3	2, 400		123, 000
							取水口	×	×	×	×	×	×	×	×	5. 0	35. 5	1, 900		97, 000
51	49	上井戸沢 3	大熊町	R5. 8. 3	晴	0. 28	流入口	0. 48	0. 1	16. 0	23. 2	15	<1	—	7. 3	58. 8	9, 300	341, 000	帰還困難区域外	
							湖心部	—	—	—	—	—	—	—	10. 0	66. 9	28, 000	1, 715, 000		
								20. 0	63. 9	15, 000										
								30. 0	58. 0	360										
							取水口	0. 98	0. 1	16. 5	19. 2	14	<1	—	10. 0	66. 1	28, 000	1, 228, 000		
															20. 0	61. 9	5, 000			
30. 0	52. 9	660																		
54	50	鮎沢第 2	大熊町	R5. 7. 31	晴	0. 57	流入口	1. 28	0. 5	12. 5	35. 7	13	<1	—	8. 0	51. 1	49, 000	2, 540, 000	帰還困難区域外 (R4. 6. 30解除)	
							湖心部	—	—	—	—	—	—	—	10. 0	54. 0	65, 000	13, 701, 000		
								20. 0	49. 7	65, 000										
								30. 0	43. 7	68, 000										
							取水口	2. 08	0. 5	16. 2	20. 2	14	1	1. 0	10. 0	58. 8	68, 000	17, 276, 000		
															20. 0	56. 9	73, 000			
															30. 0	56. 9	81, 000			
40. 0	56. 1	92, 000																		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果						底質調査結果				備考	
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度(Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs
55	51	万右衛門ため池	大熊町	R5. 8. 3	晴	0. 31	流入口	0. 89	0. 1	16. 8	16. 9	17	<1	—	4. 0	46. 6	2, 600	75, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	10. 0	65. 8	14, 000	1, 986, 000		
														20. 0	57. 4	27, 000			
														30. 0	56. 5	78			
							取水口	0. 95	0. 1	33. 4	12. 1	24	<1	—	10. 0	63. 3	8, 900	3, 397, 000	
															20. 0	54. 4	6, 300		
															30. 0	71. 3	14, 000		
															40. 0	58. 7	42, 000		
36	52	北郷第二(旧北郷第1)	富岡町	R5. 7. 19	雨	0. 39	流入口	1. 19	0. 5	50. 0	5. 2	6	<1	—	5. 7	51. 3	15, 000	559, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	60. 6	18, 000	869, 000	
							取水口	1. 81	0. 5	46. 0	10. 8	12	<1	—	9. 0	62. 6	20, 000	829, 000	
38	53	北郷第三(旧北郷第2)	富岡町	R5. 7. 19	小雨	0. 37	流入口	1. 49	0. 5	33. 0	9. 5	12	<1	—	4. 3	40. 8	10, 000	413, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	4. 7	43. 0	9, 500	374, 000	
							取水口	1. 50	0. 5	32. 0	8. 7	11	<1	—	5. 0	43. 7	13, 000	527, 000	
40	54	宮の前	富岡町	R5. 7. 19	曇	0. 44	流入口	0. 46	0. 1	38. 0	4. 8	7	<1	—	7. 0	46. 6	3, 300	180, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	10. 0	53. 1	3, 900	405, 000		
														20. 0	49. 1	2, 200			
							取水口	1. 34	0. 5	40. 0	8. 4	5	<1	—	10. 0	52. 8	4, 600	303, 000	
															20. 0	45. 7	490		
30. 0	50. 5	59																	
41	55	前沢田	富岡町	R5. 7. 21	雨	0. 36	流入口	1. 05	0. 5	20. 3	16. 7	36	<1	—	9. 0	38. 5	6, 200	522, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	10. 0	52. 5	17, 000	1, 957, 000		
														20. 0	48. 9	13, 000			
							取水口	1. 41	0. 5	18. 9	16. 4	43	<1	—	10. 0	55. 9	5, 600	438, 000	
															20. 0	53. 8	2, 100		
							30. 0	51. 1	37										
42	56	椿屋第3	富岡町	R5. 7. 21	曇時々雨	0. 44	流入口	1. 24	0. 5	22. 5	17. 6	39	<1	—	10. 0	55. 5	6, 100	813, 000	帰還困難区域外
															20. 0	48. 7	5, 600		
															30. 0	42. 6	1, 000		
							湖心部	—	—	—	—	—	—	—	6. 0	47. 2	5, 000	233, 000	
															10. 0	58. 9	8, 500	2, 591, 000	
							取水口	2. 09	0. 5	26. 0	16. 8	38	<1	—	20. 0	59. 2	13, 000		
															30. 0	58. 1	18, 000		
															40. 0	56. 3	9, 500		

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モニ No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果							底質調査結果				備考		
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)	放射性物質 底質表面濃度 (Bq/m ²)			
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs	¹³⁷ Cs			
43	57	家老	富岡町	R5. 7. 18	晴	0. 51	流入口	4. 21	0. 5	>100	6. 3	1	<1	—	10. 0	49. 1	7, 500	498, 000	帰還困難区域外		
							湖心部	—	—	—	—	—	—	—	10. 0	52. 9	22, 000	3, 145, 000			
								20. 0	50. 5	29, 000											
								取水口	3. 48	0. 5	>100	6. 6	1	<1	—	4. 3	31. 9			4, 400	181, 000
44	58	西沢	富岡町	R5. 7. 19	曇	0. 26	流入口	2. 55	0. 5	69. 4	1. 8	3	<1	—	10. 0	49. 5	7, 400	1, 062, 000	帰還困難区域外		
							湖心部	—	—	—	—	—	—	—	10. 0	51. 9	8, 800			1, 251, 000	
								20. 0	48. 4	9, 300											
								30. 0	50. 9	1, 800											
								取水口	2. 62	0. 5	70. 0	3. 5	7	<1	—	10. 0	51. 7	6, 100			514, 000
							20. 0		51. 8	2, 400											
							30. 0		50. 6	29											
							45	59	申田第二(旧申田)	富岡町	R5. 7. 19	曇/晴	0. 61	流入口	0. 85	0. 1	26. 8	13. 1		12	<1
湖心部	—	—	—	—	—	—								—	10. 0	59. 9	34, 000	6, 897, 000			
	20. 0	57. 9	48, 000																		
	30. 0	55. 5	60, 000																		
	取水口	1. 12	0. 5	26. 4	15. 2	13								<1	—	10. 0	45. 9		14, 000	5, 615, 000	
20. 0		41. 9	19, 000																		
30. 0		43. 5	36, 000																		
86	60	菅田第 1	飯舘村	R5. 8. 7	晴	0. 55								流入口	0. 04	表層	27. 1	29. 9	—	—	—
							湖心部	—	—	—	—	—	—	—	6. 3	73. 0	13, 000	239, 000			
							取水口	0. 06	表層	36. 1	12. 0	—	—	—	4. 7	67. 6	20, 000	341, 000			
87	61	大北	飯舘村	R5. 8. 9	晴	0. 22	流入口	0. 15	0. 1	>100	8. 4	1	<1	—	10. 0	58. 4	3, 300	610, 000	帰還困難区域外		
							湖心部	—	—	—	—	—	—	—	5. 7	36. 8	740			43, 000	
								取水口	0. 03	表層	51. 3	17. 1	—	—	—	10. 0	67. 6				3, 500
									20. 0	41. 8	920										
									30. 0	35. 3	470										

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ 二 No.		名 称	市町村	採取日	天候	空間 線量率 (μSv/h)	測定位置	水質調査結果						底質調査結果				備考	
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs
88	62	大宮作ため池	飯舘村	R5. 8. 8	曇 雨	0. 22	流入口	1. 06	0. 5	39. 4	8. 2	13	<1	—	10. 0	71. 8	18, 000	3, 313, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	20. 0	70. 2	48, 000		
															30. 0	69. 2	30, 000		
															10. 0	70. 4	19, 000	1, 596, 000	
							取水口	2. 17	0. 5	33. 4	10. 4	9	<1	—	20. 0	64. 3	21, 000		
															10. 0	58. 8	17, 000		
20. 0	56. 4	11, 000																	
89	63	山田	飯舘村	R5. 8. 8	曇	0. 26	流入口	0. 84	0. 1	65. 5	7. 7	7	<1	—	4. 0	23. 0	260	15, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	44. 9	1, 200	97, 000	
							取水口	0. 21	0. 1	83. 0	4. 1	2	<1	—	3. 3	48. 0	1, 800	44, 000	
90	64	野沢	飯舘村	R5. 8. 8	小雨	0. 25	流入口	0. 05	表層	76. 5	3. 2	—	—	—	5. 3	76. 3	25, 000	344, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	3. 0	55. 1	5, 800	106, 000	
							取水口	0. 17	0. 1	28. 2	36. 2	18	<1	—	3. 0	69. 2	9, 900	113, 000	
91	65	大火第 1	飯舘村	R5. 8. 9	曇	0. 22	流入口	0. 87	0. 1	74. 4	3. 7	1	<1	—	10. 0	49. 0	7, 400	527, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	62. 3	12, 000	1, 733, 000	
															20. 0	59. 0	13, 000		
															30. 0	54. 7	8, 300		
							取水口	0. 51	0. 1	52. 5	7. 0	9	<1	—	3. 3	43. 6	4, 000	109, 000	
92	66	滝下	飯舘村	R5. 8. 10	晴	0. 52	流入口	0. 95	0. 1	>100	0	<1	<1	—	3. 7	52. 4	14, 000	340, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	64. 5	31, 000	12, 794, 000	
															20. 0	66. 2	51, 000		
															30. 0	67. 7	130, 000		
															40. 0	68. 5	110, 000		
							取水口	0. 82	0. 1	>100	0	1	<1	—	6. 3	64. 7	42, 000	1, 162, 000	
93	67	洞ノ入	飯舘村	R5. 8. 8	曇 雨	0. 28	流入口	1. 13	0. 5	41. 3	12. 3	4	<1	—	6. 3	52. 9	16, 000	641, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	10. 0	56. 7	19, 000	1, 429, 000	
															20. 0	55. 3	6, 300		
															30. 0	51. 6	140		
							取水口	1. 79	0. 5	38. 6	10. 9	4	<1	—	5. 7	50. 8	35, 000	1, 370, 000	
94	68	所久保	飯舘村	R5. 8. 9	晴	0. 52	流入口	1. 20	0. 5	29. 5	16. 4	8	<1	—	6. 3	35. 7	1, 100	69, 000	帰還困難区域外
							湖心部	—	—	—	—	—	—	—	8. 2	34. 9	1, 200	104, 000	
							取水口	1. 72	0. 5	25. 4	23. 1	14	<1	—	6. 7	39. 6	1, 900	97, 000	

別添 1 令和5年度 帰還困難区域外のため池調査結果

－：調査対象外、×：調査不可

モ ニ No.		名 称	市町村	採取日	天候	空間 線量率 (μ Sv/h)	測定位置	水質調査結果						底質調査結果				備考													
								全水深 (m)	採水深 (m)	透視度 (cm)	濁度 (度)	SS (mg/L)	放射性物質濃度 (Bq/L)		採取 深さ (cm)	含水率 (%)	放射性物質濃度 (乾泥) (Bq/kg)		放射性物質 底質表面濃度 (Bq/m ²)												
													¹³⁷ Cs (ろ過前)	¹³⁷ Cs (ろ過後)			¹³⁷ Cs		¹³⁷ Cs												
95	69	水境	飯舘村	R5. 8. 7	晴	0. 12	流入口	0. 12	0. 1	30. 3	24. 0	33	<1	—	5. 7	25. 8	350	26, 000	帰還困難区域外												
							湖心部	—	—	—	—	—	—	10. 0	50. 1	2, 300	593, 000														
														20. 0	51. 4	3, 300															
														30. 0	59. 1	4, 300															
取水口	0. 69	0. 1	26. 8	16. 5	14	<1	—	5. 7	34. 4	870	50, 000																				
96	70	入山田	飯舘村	R5. 8. 8	曇	0. 19	流入口	0. 69	0. 1	60. 0	9. 7	5	<1	—	4. 7	37. 0	280	13, 000	帰還困難区域外												
							湖心部	—	—	—	—	—	—	8. 7	35. 9	860	71, 000														
							取水口	1. 09	0. 5	41. 9	9. 1	6	<1	—	5. 7	43. 2	950	43, 000													
97	71	小山田入	飯舘村	R5. 8. 7	晴	0. 42	流入口	0. 29	0. 1	16. 2	24. 0	29	<1	—	10. 0	56. 9	4, 600	360, 000	帰還困難区域外												
							湖心部	—	—	—	—	—	—	—	4. 7	54. 6	4, 500			126, 000											
																					取水口	0. 47	0. 1	41. 5	7. 6	12	<1	—	4. 7	54. 8	9, 200
																		流入口			0. 05	表層	25. 2	13. 5	—	—	—	4. 0	49. 0	980	29, 000
湖心部	—	—	—	—	—	—	—	4. 3	37. 0	420	17, 000																				
取水口	0. 05	表層	39. 3	9. 9	—	—	—	5. 3	50. 2	620	22, 000																				
99	73	冬住	飯舘村	R5. 8. 8	雨 晴	0. 30	流入口	×	×	×	×	×	×	×	3. 7	63. 5	11, 000	170, 000	帰還困難区域外												
							湖心部	—	—	—	—	—	—	10. 0	70. 5	25, 000	2, 543, 000														
														20. 0	72. 1	46, 000															
														30. 0	68. 2	8, 100															
取水口	1. 27	0. 5	26. 9	18. 3	25	<1	—	4. 0	40. 2	9, 000	323, 000																				
100	74	笹の沢第 3	飯舘村	R5. 8. 4	晴	0. 40	流入口	0. 83	0. 1	37. 7	5. 2	8	<1	—	5. 0	50. 0	2, 800	91, 000	帰還困難区域外												
							湖心部	—	—	—	—	—	—	—	5. 0	54. 6	3, 000	86, 000													
							取水口	0. 71	0. 1	35. 7	6. 8	9	<1	—	3. 7	46. 8	4, 100	117, 000													